



WCS Gate Shaft Bench

Gate Shaft Bench Parts



1. Side Panels (quantity: 2)
2. Rails (quantity: 2)
3. SPM gate shafts (quantity: 11)
4. 3 ½ inch torx head screws (quantity: 8)
5. Torx Driver bit (quantity: 1)



World Cup Supply, Inc.

226 Industrial Drive
Bradford, Vermont 05033 USA

(800) 555-0593

www.worldcupsupply.com

WCS Gate Shaft Bench Assembly Direction

1. Attach the rails (#2) with four of the 3½ inch Torx screws (#4) to one of the side panels (#1). Please use the Torx driver bit included (#5). Be careful not to over tighten and that the pre-drilled holes are aligned.



2. Lay the end panel down with the rails vertical.



3. Insert the SPM gate shafts into the end panel.



4. Loosely attach the second panel with the remaining Torx screws on top of the vertical rails and gate shafts. Align the SPM shafts so that they are positioned in the side panel properly.



6. When all gate shafts are in place, tighten the last four Torx screws and enjoy!



World Cup Supply, Inc.

3 Ely Road, Suite 1
Fairlee, Vermont 05045 USA

(800) 555-0593

www.worldcupsupply.com